

Blackpool Council Licensing Service

Representation made by a Responsible Authority
In support of an application for the Review of an existing
Premises Licence or Club Premises Certificate

Responsible Authority making representation

Name of Responsible Authority	Health and Safety Enforcement			
Name of Officer <i>(please print)</i>	Gareth Shaw			
Contact telephone number	01253 478315			
Date representation made	21	05	14	
Do you consider mediation appropriate			YES	NO

Name of Responsible Authority / Applicant who requested a review of this Licence

Weights and Measures

Premises Details

Premises Name	Whitegate Food and Wine
Address	99 Whitegate Drive
	Blackpool
Post Code	FY3 9BY

Details of your representation in support of the review application

(Please reference & attach supporting any documentation)

This section would like to bring to the attention of the authorities the findings of a visit carried out on the 17th of January 2013. The detail which are shown in the pictures below.



1) Above shows dangerous electrical installations.




2) Cables trailing across walkways and under carpet and consumer units behind refrigeration.



3) Cluttered work area and blocked cellar entrance.




3) Damp ingress and extremely poorly maintained lighting and associated electrical systems.



4) Obstructed fire equipment.



5) Damaged socket and an old electrical fuse box left open.



6) Waste thrown under counter.



7) Poorly maintained floor areas.



8) Broken freezer equipment.



9) Collapsed ceiling exposing dangerous and poorly maintained electrical installations.



10) Flooded and very poorly maintained flooring areas.



11) Damage ventilation fan exposing live electrical connections.



12) Broken light switch fixed with parcel tape.



13) Cluttered, poorly maintained and filthy hand wash facilities.



14) Damp is prevalent in most areas and left without any actions or plan to action.



15) Accumulation of waste.



16) Clutter yard area and overflowing waste bin.



17) Further poorly maintained flooring, lighting and also cluttered shop area.



18) Cabling across walkways waste accumulation, unsealed wooden floors, wedged fire separation doors and further cluttered storage areas to the rear.



Further to the above a prohibition notice was served in respect of a collapsing floor area and improvement notices in respect of electrical maintenance and gas safety certification.

. The electrical mains situation was reported to Electricity Northwest and they visited to make safe.