

Photographs taken by Senior Public Protection Officer, Gareth Shaw during a visit to Bar 137 on the 24th of January 2014.



- 1) Above shows electrical installations and equipment that required either making good or further investigation by a competent electrician.

Photographs taken by Senior Public Protection Officer, Gareth Shaw during a visit to Bar 137 on the 24th of January 2014.




2) Drainage overflow spilling filthy water/effluent into cellar areas.

Photographs taken by Senior Public Protection Officer, Gareth Shaw during a visit to Bar 137 on the 24th of January 2014.



3) Waste accumulation and further filth in cellar areas.

Photographs taken by Senior Public Protection Officer, Gareth Shaw during a visit to Bar 137 on the 24th of January 2014.



4) Electrical cables joined in public area with no physical protection.

5) Improvement notices were served to deal with all the issues above.