

## CENTRAL LIBRARY PHOTOGRAPHS OF CONDITION

Prepared by Property Services – January 2021



West elevation (Abingdon Street) and the small store off the big room. The leak is in the right corner.



The top left where the scaffolding is visible, the flat lead section on the bay is above the area of the leak in the store



Central Roof leaks image - areas of know water egress and damp.